

Fig. 1



GBLON, SPIVAK, ET AL DOCKET #: 205114US2
INV: Masumi YOSHINO, et al SHEET 2 OF 11

Fig. 2









Fig. 3












Fig. 5




OBLON, SPIVAK, ET AL DOCKET #: 205114US2
INV: Masumi YOSHINO, et al SHEET 6 OF 11

Fig. 6




Ţ

BLON, SPIVAK, ET AL DOCKET #: 205114US2 INV: Masumi YOSHINO, et al SHEET 7\_OF\_11\_



ON, SPIVAK, ET AL DOCKET #: 205114US2 INV: Masumi YOSHINO, et al SHEET 8 OF 11



Solve Printer Online Support Confirm that paper is specified size. Power off and pull out paper slowly. Contact E mail support when problem is not eliminated by any proposed workarounds. Try following workarounds: E Mail Support -ile Edit View Favorites Help ht tp://\*\*\* Address

Fig. 10

BX	
Name	
E-mail	
Address	
Phone	
Model	
Serial No.	
o s	
Driver Version	
Application activated when problem arises  Data having problem  Name of application	
Connection port URI	
Result of processing	
Description of status of problem	
LFM	

Fig. 11

